PAOF Software Version 4.3.7 Released

Version 4.3.7 features one change from its predecessor, 4.3.4. In some applications, ambient noise around the phone location was picked up by the handset transmitter and interpreted as S.I.T. tones on the line. This resulted in the phone disconnecting the call and refunding the coin within the first 20 seconds of the call. To address these situations, 4.3.7 has enhanced S.I.T. tone detection that will ignore any noise exterior to the phone.

All the previous enhancements of PAOF release 4.3.4 are included in this newest release.